

Table de conversion Pouce " (fraction et proportion) — millimètres

Pouce (par fraction)	Pouce (en proportion)	mm	Pouce (par fraction)	Pouce (en proportion)	mm
1/32	0,03125	0,79375	17/32	0,53125	13,49375
1/16	0,0625	1,5875	9/16	0,5625	14,2875
3/32	0,09375	2,38125	19/32	0,59375	15,08125
1/8	0,125	3,175	5/8	0,625	15,875
5/32	0,15625	3,96875	21/32	0,65625	16,66875
3/16	0,1875	4,7625	11/16	0,6875	17,4625
7/32	0,21875	5,55625	23/32	0,71875	18,25625
1/4	0,25	6,35	3/4	0,75	19,05
9/32	0,28125	7,14375	25/32	0,78125	19,84375
5/16	0,3125	7,9375	13/16	0,8125	20,6375
11/32	0,34375	8,73125	27/32	0,84375	21,43125
3/8	0,375	9,525	7/8	0,875	22,225
13/32	0,40625	10,31875	29/32	0,90625	23,01875
7/16	0,4375	11,1125	15/16	0,9375	23,8125
15/32	0,46875	11,90625	31/32	0,96875	24,60625
1/2	0,5	12,7	1	1	25,4

Cette table peut être obtenue à l'adresse Internet : www.connais.org/pouce-mm.html